

CHEMICAL AND MAINTENANCE REQUEST

DATE 10-11-91NUMBER 2816-6TO: ☒ PAINT STORES ☒ MAINTENANCE☒ HAZ WASTE

FROM: PROCESS CONTROL LABORATORY

SUBJECT: CHEMICAL PROCESS TANKS

COPIES TO: ☒ SUPERVISOR, DEPT 6402 ☐ FILE

REFERENCE: CP 10.001

PLEASE FURNISH MATERIAL AND/OR SERVICES AS NOTED

TANK NO.	<u>97</u>	BUILDING	<u>1</u>	POST LOCATION	<u>2-14</u>	DEPARTMENT	<u>6402</u>
LAST ANALYSIS, DUMPS ONLY	MATERIAL DESCRIPTION				DPM NO.	QUANTITY	
<u>Ti = 148.69 lbs/kGal</u>	<u>NITRIC ACID</u>				<u>948</u>	<u>390 Gals</u>	
<u>s/B = 140 lbs/kGal</u>	<u>HYDROFLUORIC ACID</u>				<u>5466</u>	<u>189 Gals</u>	
<u>max</u>	<u>BUTYL CELLOSOLVE</u>				<u>509</u>	<u>140 Gals</u>	
	<u>SODIUM LAURYL SULFATE</u>				<u>2500</u>	<u>6 Gals</u>	
<input type="checkbox"/> ADDITION <input checked="" type="checkbox"/> REFILL <input checked="" type="checkbox"/> DUMP <input type="checkbox"/> REPAIR <input checked="" type="checkbox"/> CLEAN <input type="checkbox"/> RECHARGE DEIONIZER <input checked="" type="checkbox"/> PUMP OUT <u>62</u> IN.		FILL TO <u>10"</u> WITH <input checked="" type="checkbox"/> TAP WATER <input type="checkbox"/> DEIONIZED WATER		DISPOSE OF <u>3478</u> GALLONS TO: <input type="checkbox"/> SEWER <input checked="" type="checkbox"/> DISPOSAL CO. <input type="checkbox"/> MARKED DRUMS			
SPECIAL INSTRUCTIONS: <u>CO TAG 8052</u>							
<u>1. Pump out 62" of soln. (approx. 3478 Gals) leaving 4" of solution in the tank as "seed".</u>							
<u>2. Maintain solution agitation during the pump-out operation.</u>							
<u>3. Fill tank half full with tap water.</u>							
<u>4. Add the required chemicals, then fill with water to correct working level.</u>							
<input type="checkbox"/> COORDINATE DUMP WITH DUMP(S) OF TANK(S) NO.(S) <u>correct working level.</u>							
<input checked="" type="checkbox"/> IT IS REQUESTED THAT ACTION BE COMPLETED BY <u>2:30 p.m.</u> ON <u>10-14-91</u>							
REQUESTED BY		APPROVED BY		ACTION COMPLETED BY DEPT			
<u>[Signature]</u>		<u>[Signature]</u>		TIME _____ DATE _____			

CHEMICAL AND MAINTENANCE REQUEST

DATE 10-11-91NUMBER 2816-6TO: ☒ PAINT STORES ☒ MAINTENANCE ~~XXXXXXXXXX~~

FROM: PROCESS CONTROL LABORATORY

SUBJECT: CHEMICAL PROCESS TANKS

COPIES TO: ☒ SUPERVISOR, DEPT 6402 ☐ ☒ FILE

REFERENCE: CP 10.001

PLEASE FURNISH MATERIAL AND/OR SERVICES AS NOTED

TANK NO. <u>97</u>	BUILDING <u>1</u>	POST LOCATION <u>2-14</u>	DEPARTMENT <u>6402</u>
LAST ANALYSIS, DUMPS ONLY	MATERIAL DESCRIPTION	DPM NO.	QUANTITY
$T_i = 148.69 \text{ lbs/KGal}$	NITRIC ACID	948	390 Gals
$S/B = 140 \text{ lbs/KGal}$	HYDROFLUORIC ACID	3466	189 Gals
max	BUTYL CELLOSOLVE	509	140 Gals
	SODIUM LAURYL SULFATE	2500	6 Gals
<input type="checkbox"/> ADDITION <input checked="" type="checkbox"/> REFILL <input checked="" type="checkbox"/> DUMP <input type="checkbox"/> REPAIR <input checked="" type="checkbox"/> CLEAN <input type="checkbox"/> RECHARGE DEIONIZER <input checked="" type="checkbox"/> PUMP OUT <u>62</u> IN.		FILL TO <u>10"</u> WITH <input checked="" type="checkbox"/> TAP WATER <input type="checkbox"/> DEIONIZED WATER DISPOSE OF <u>3478</u> GALLONS TO: <input type="checkbox"/> SEWER <input checked="" type="checkbox"/> DISPOSAL CO. <input type="checkbox"/> MARKED DRUMS	
SPECIAL INSTRUCTIONS: CO TAG 8052			
1. Pump out 62" of soln. (approx. 3478 Gals) leaving 4" of solution in the tank as "seed".			
2. Maintain solution agitation during the pump-out operation.			
3. Fill tank half full with tap water.			
4. Add the required chemicals, then fill with water to correct working level.			
<input type="checkbox"/> COORDINATE DUMP WITH DUMP(S) OF TANK(S) NO.(S) <u> </u> <input checked="" type="checkbox"/> IT IS REQUESTED THAT ACTION BE COMPLETED BY <u>2:30 p.m.</u> ON <u>10-14-91</u>			
REQUESTED BY <u> </u>	APPROVED BY <u> </u>	ACTION COMPLETED BY DEPT <u> </u>	
		TIME <u> </u> DATE <u> </u>	